

Employees

Katie Norton,Facilities Manager



Shawn Goshorn,Maintenance & Repair





Darian Couturier,
Lead Maintenance & Repair



Mary Morris, Mail Clerk

Job Responsibilities

▶ Facilities Manager

- Manage: Print Production, Mail Room, and Maintenance of City Hall
- Coordinate: Printing standards, Access security, renovations/remodels, and Communications
- Lead: City Facility Managers, City Hall Safety
 & Security, and Employee events



Job Responsibilities

► Maintenance & Repair

- Manage: City Hall, Police Department,
 Police Elm St. location & 6 Fire Houses
- Maintenance & Repair: Equipment, preventative maintenance, general construction, painting, minor electrical, plumbing, fabrication, boiler, HVAC, safety equipment, asbestos mitigation, installation, furniture
- Grounds: Snow removal, salting, irrigation, garbage, recycling, lighting, repairs, concrete and masonry
- If a department needs help, Darian & Shawn are there





Job Responsibilities

Mailroom Clerk

- Mail: 4 P.O. boxes (Utility bills, Property tax, Income tax, & General), 10 N. Division mail, opening, organizing, postage
- Pick up & Delivery: All City Hall internal departments, 16 external buildings
- Security: Commission info desk, screening table, election staff





Current Project

- City Hall terra cotta pediment façade replacement
- Summer of 2017: Northeast corner fell
 - East Pediment: Replaced in spring of 2021
 - South Pediment: Replaced in spring 2022
 - West Pediment: Replaced in spring 2023









Current Project


- City Hall full building generator
- City Hall & PD share heat
- Refurbish previous Police Department diesel generator
- Will run everything in City Hall minus the chiller





Current Project

- Covid-19 Preparedness
- Implement safety protocols
- Manage disinfecting checklists for all city facilities
- Coordinate with CSO to supply disinfectant and PPE for all city facilities



- City Hall exterior condition assessment
- Fall of 2017

Ta	ble 1. Engine	er's Opinion	of Proba	ble Cost				
Repair Ta				Culatatala	Total ¹			
Item ² Description	Quantity	Unit	Un	it Cost	Subtotals	Estimated R	ange of Repair Cost	
riority 2 Repairs -recommend complete y 2024						\$67,800	to	\$86,000
imestone								
Grind and point failed mortar joints between limestone units and at stairstep cracks								
1.	1500	LF	\$	10	\$15,000	\$15,000		\$18,800
Pin and dutchman repairs at full height cracks	20	EA	Ś	750	\$15,000	\$15,000		\$18,800
Remove wood blocks from horizontal surface of limestone water table units and patch with approved material.	60	EA	\$	75	\$4,500	\$4,500		\$5,700
Grind and repoint mortar joints between limestone water table units. Install backer rod and sealant in all upward facing joints.	00	LA	,	73	\$4,500	\$4,500		\$3,700
4.	260	LF	\$	14	\$3,640	\$3,700		\$4,600
Rout and seal cracks within limestone units. 5.	30	LF	\$	25	\$750	\$800		\$1,000
6. Patch previously spalled areas	15	EA	\$	50	\$750	,		\$1,000
rick Masonry								
Remove loose materials and rebuild masonry at upper segment of chimney stack								
7.	100	SF	\$	85	\$8,500	\$8,500		\$10,700
Repair cracked/spalled concrete chimney cap								
8. Сар	5	SF	\$	85	\$425	\$500		\$600
ealant								
Remove and replace sealant at the following locations								
Per imeter window sealant at remaining a original windows and doors	525	LF	\$	10	\$5,250	\$5,300		\$6,600
h. Metal projection terminations	1450	LF	Š	10	\$14,500	\$14,500		\$18,200


- City Hall exterior condition assessment
- Fall of 2017

	Т	able 1. Engin	eer's Opinion o	f Proba	ble Cost				
	Repair T		gco. 5 opc			Total ¹			al ¹
Item ²	Description	Quantity	Unit	Uni	it Cost	Subtotals	Estimated Range of Repair Cos		
Priorit	y 3-recommend complete by 2027						\$373,200	to	\$466,600
Limesto									
1.	Clean surface of stained limestone units with a light water blast and use of a biologic cleaner.	13500	SF	\$	4	\$54,000	\$54,000		\$67,500
		.5500	5.	Ť		\$5.,000	45 1,000		\$0.,500
Brick Ma	sonry								
2.	Grind and repoint all mortar joints in the brick masonry to eliminate the "smear" coating	7000	SF	ć	22	\$4E4.000	¢454.000		¢402 E00
3.	Remove and replace cracked brick units.	600	SF EA	\$ \$	22 15	\$154,000 \$9,000	\$154,000 \$9,000		\$192,500 \$11,300
٥.	remove and replace a dated by factames.	600	EA	Ş	13	\$9,000	\$9,000		\$11,300
Terra Co	ntta								
	Following repairs, re-inspect terra cotta elements every five years to document evidence of continued corrosion related distress.				5 500	65 500	65 500		£4.000
4.	Per for m a light pressure cleaning of the	1	EA	\$	5,500	\$5,500	\$5,500		\$6,900
5.	coated areas, and provide touchup, recoating in failed areas.	13500	SF	\$	6	\$81,000	\$81,000		\$101,300
6.	Recoat surfaces, but not joints, in coor dination with grinding and repointing program.	13500	SF	S	4	\$54.000	\$54,000		\$67,500
ŭ.	Grind and point all mortar joints between window head and sill units. Provide backer rod and sealant in all upward facing mortar	15500	J.	Ť		43 1,000	73 1,000		707,300
7.	joints	650	LF	\$	14	\$9,100	\$9,100		\$11,400
Miscellar									
9	Remove bird deterrent spikes and clean associated surfaces of debris.	50	LF	\$	25	\$2,750	\$2,800		\$3,500
10	Clean iron hand rails and coat with corrosion inhibiting coating.	150	LF	\$	25	\$3,750	\$3,800		\$4,700
						. ,	. ,		. ,

City Hall retaining wall replacement

Spring of 2017








itelli	Qty.	Offic		Official		TOTAL
OPTION 3C - Remove Wall and Replace with CMU	Backing Wall	and Pargeted I	inish			
Mobilization	1	LS	s	5,000.00	s	5,000.00
Site wide Construction Barrier Fencing	600	LF	\$	7.00	S	4,200.00
Traffic Control Devices	1	LS	\$	500.00	S	500.0
Demolish Wall and Foundation	1	LS	\$	13,000.00	S	13,000.00
Salvage and repair Existing Wall Cap Units	1	LS	\$	3,500.00	S	3,500.0
Excavate Demolished Material and Haul Off-site	125	CYD	\$	23.00	S	2,875.0
18" wide CIP Concrete Base and Footing	450	LFT	\$	170.00	\$	76,500.00
CMU Backing Wall	850	SF	\$	11.00	S	9,350.0
Pargeted Finish	850	SF	\$	40.00	S	34,000.0
Reset existing Wall Caps	450	LFT	\$	9.00	S	4,050.0
Wall Subdrain and 6A aggregate (2' wide)	450	LFT	\$	50.00	\$	22,500.0
Wall Subdrain Outlet connection to Existing Storm (Manhole in south walk and manhole in east parking	1	LS	\$	2,200.00	\$	2,200.0
Repair/replacement of adjacent hardscapes	1	Allowance	S	10.000.00	S	10.000.0
Repair and Restore Lawn Irrigation	2.500	SE	Š	0.75	S	1.875.0
Topsoil and Fine Grade	260	SY	Š	4.60	Š	1,196.0
Turf Seeding	2,400	SF	\$	0.15	\$	360.0
OPTION 3C Subtotal					\$	191,106.00
Contingency: +15%					\$	28,665.9
A&E Fees: +/- 10%					\$	21,977.1
OPTION 3C Total					\$	241,749.09
NOT INCLUDED : Subsurface explorations Modifications to existing Utilities.						

(Connect to manhole in Division Street and manhole to east)

ADD \$2000



- Roof renovation
 - Membrane roof, warranty expires August 2022
- Lighting improvements
 - Old light fixtures, dark atmosphere
- Interior painting
 - Last done in early 90's, dark, peeling, & dirty
- Carpet replacement
 - Current carpet installed in the 1982 remodel
- Refurbish 3 Air Handlers
 - Installed in 1982 remodel
- Solar Power

Large Consumers Energy bill, clean way to supplement electricity

